

Equotip 550 Leeb

How to create specific conversion curves to test exotic metals

Conversion curves for nine different material groups are available on all of Proceq's Equotip Leeb testers and cover the vast majority of applications. If an exotic material is to be tested which is not covered, there are different options depending on the instrument in use for creating a new specific conversion curve.

Either an existing curve can be modified by two different methods, or a completely new curve can be created and stored on the instrument for direct use. These curves can not only be stored, but also shared with others. Download the Equotip 550 operating instructions for detailed instructions: www.proceq.com/downloads



→ Go to product website

→ Contact us